

# FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF	LC	ID		YW		Transfer		Compost		SLAS	X	COUNTY: Harnett
Closed MSWLF	HE	W		White goods		Incin		T&P		FIRM		PERMIT NO.: SLAS 43-03
CDLF	Tire T Colle	%P/ ction		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

## **FACILITY NAME AND ADDRESS:**

Gerald Temple Septic Tank Service 1636 Temple Road Bunnlevel, NC 28323

**GPS COORDINATES**: N: 35.31833 W: -78.84472

## **FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Gerald Temple Telephone: (910) 893-4953

Email address: N/A Fax: (910) 893-3184

# **FACILITY CONTACT ADDRESS:**

N/A

## **PARTICIPANTS**:

Connie Wylie, Gerald Temple

# **STATUS OF PERMIT**:

Active

#### **PURPOSE OF SITE VISIT:**

Repermit

# **STATUS OF PAST NOTED VIOLATIONS:**

N/A

## **OBSERVED VIOLATIONS**

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

# FACILITY COMPLIANCE INSPECTION REPORT

# Division of Waste Management Solid Waste Section

Page 2 of 2

# **ADDITIONAL COMMENTS**

- 1. Received the renewal application for this permit.
- 2. No land application has occurred in years discussed pursuing "inactive status".
- 3. The required signs are posted and the access road is adequate.
- 4. Winter cover crop is established.
- 5. Additional field markers would be needed if site was utilized (also re-GPS at that time).

Please contact me if you have any questions or concerns regarding this inspection report.

Connie S. Wylie

Regional Representative

Phone: (910) 433-3352